



IM

April 11, 2005

Express Mail Label No. EV 570 162 539 US

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Re:

U.S. Patent No. 6,709,995

Issued March 23, 2004

For: Method of Prepregging with Resin and Novel

Prepregs Produced by Such Method

Joel A. Dyksterhouse, Inventor

Dear Sir:

We have noted, in proofreading the subject patent, the errors listed on the enclosed Certificate of Correction form. Our records indicate that these errors were made by our office and the Patent Office. Our check for \$100.00 is enclosed.

The corresponding location in the application of the errors in question is as follows:

The first error appears on page 1, line 28 of the application.

The second error appears on page 1, line 30 of the application.

The third error appears on page 2, line 8 (first occurrence) of the application.

The fourth error appears on page 2, line 9 of the application.

The fifth error appears on page 2, line 9 of the application.

04/13/2005 MAHMED1 00000035 6709995

Metropolitan

01 FC:1811

100.00 OP

FOR COURIER DELIVERY ONLY 5445 Corporate Drive Troy, Michigan 48098 248.641.1600 CABLE
Patents Troy, Michigan
Telex No. & Reply
287637 Harness UR
Telefacsimile 248.641.0270

The sixth error appears on page 3, line 1 of the application. The seventh error appears on page 6, line 17 of the application. The eighth error appears on page 6, line 25 of the application. The ninth error appears on page 7, line 7 of the application. The tenth error appears on page 7, line 8 of the application. The eleventh error appears on page 7, line 18 of the application. The twelfth error appears on page 9, line 6 of the application. The thirteenth error appears on page 9, line 28 of the application. The fourteenth error appears on page 12, line 20 of the application. The fifteenth error appears on page 14, line 3 of the application. The sixteenth error appears on page 17, line 29 of the application. The seventeenth error appears on page 17, line 32 of the application. The eighteenth error appears on page 18, line 3 of the application. The nineteenth error appears on page 18, line 6 of the application. The twentieth error appears on page 18, line 7 of the application. The twenty-first error appears on page 18, line 11 of the application. The twenty-second error appears on page 18, line 21 of the application. The twenty-third error appears on page 19, line 14 of the application. The twenty-fourth error appears on page 20, line 11 of the application. The twenty-fifth error appears on page 20, line 23 of the application. The twenty-sixth error appears on page 21, line 28 of the application.

The twenty-seventh error appears on page 22, line 5 of the application.

The twenty-eighth error appears on page 22, line 15 (first occurrence) of the application.

The twenty-ninth error appears on page 22, line 15 (second occurrence) of the application.

The thirtieth error appears on page 22, line 20 (first occurrence) of the application.

The thirty-first error appears on page 22, line 20 (second occurrence) of the application.

The thirty-second error appears on page 22, line 25 (first occurrence) of the application,

The thirty-third error appears on page 22, line 25 (second occurrence) of the application.

The thirty-fourth error appears on page 22, line 29 of the application.

The thirty-fifth error appears on page 22, line 35 of the application.

The thirty-sixth error appears on page 22, line 40 of the application.

The thirty-seventh error appears on page 22, line 47 of the application.

The thirty-eighth error appears on page 2, line 17, claim 58 in the amendment dated October 23, 2003.

The thirty-ninth error appears on page 2, line 17, claim 58 in the amendment dated October 23, 2003.

The fortieth error appears on page 6, line 7, claim 78 in the amendment dated July 14, 2003.

The forty-first error appears on page 6, line 13, claim 79 in the amendment dated July 14, 2003.

Please certify the enclosed Certificate of Correction and return same to us.

Very truly yours,

Charles H. Blair

Registration No. 19734 (Attorney for Applicant)

CHB/d 4052-000002/USD

PATENT NO: 6,709,995

Page 1 of 3

DATED: March 23, 2004

INVENTOR(S): Joel A. Dyksterhouse

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 1, line 53, "yams" should be -- yarns --.

Column 1, line 55, "vacuums" should be -- vacuum-bag --.

Column 2, line 3 (first occurrence), "In" should be -- in --.

Column 2, line 6, "Incompatible" should be -- incompatible --.

Column 2, line 6, after "incompatible" insert - with --.

Column 2, line 43, "using" should be - used -.

Column 5, line 14, "He" should be -- lie --.

Column 5, line 25, "R." should be - R, -.

Column 5, line 49, "Impregnating" should be -- impregnating --.

Column 5, line 50, "withstanding" should be -- withstand --.

MAILING ADDRESS OF SENDER:

Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield Hills, MI 48303

PATENT NO. <u>6,709,995</u>

No. of additional copies



PATENT NO: 6,709,995

Page 2 of 3

DATED: March 23, 2004

INVENTOR(S): Joel A. Dyksterhouse

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 5, line 65, "Coming" should be -- Corning --.

Column 7, line 17, after "in" delete -- the --.

Column 7, line 50, "Coming" should be -- Corning --.

Column 9, line 56, after "as" insert - to -.

Column 10, line 67, "pascals" should be -- Pascals --.

Column 13, line 65, "Is" should be -- is --.

Column 14, line 2, "Coming, Coming" should be -- Corning, Corning --.

Column 14, line 10, "dimensions" should be -- dimension --.

Column 14, line 16, "wraps." should be -- wraps, --.

Column 14, line 17, "place" should be -- placed --.

Column 14, line 26, "Coming, Coming" should be -- Corning, Corning --.

Column 14, line 41, "Coming" should be -- Corning --.

Column 15, line 33, "Into" should be -- into --.

Column 15, line 59, "Coming, Coming" should be -- Coming, Comning --.

Column 16, line 13, "place" should be - placed --.

Column 16, line 57, "Coming, Coming" should be -- Coming, Corning --..

MAILING ADDRESS OF SENDER:

Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield Hills, MI 48303 PATENT NO. 6,709,995



PATENT NO: 6,709,995

Page 3 of 3

DATED: March 23, 2004

INVENTOR(S): Joel A. Dyksterhouse

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 17, line 7, "dimensions" should be -- dimension --.

Column 17, Table, line 3 (first occurrence), "95% C.I." should be -- 95% C.L. --

Column 17, Table, line 3 (second occurrence), "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 8 (first occurrence), "95% C.I." should be -- 95% C.L. --

Column 17, Table, line 8 (second occurrence), "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 13 (first occurrence), "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 13 (second occurrence), "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 16, "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 20, "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 25, "0.130" should be -- 0.130" --.

.Column 17, Table, line 33, "64/1" should be -- 64.1 --.

Column 19, line 26, "substantially," should be -- substantially --.

Column 19, line 26, "void" should be -- voids --.

Column 20, line 41, "Inlet" should be -- inlet --.

Column 20, line 51, "pascals" should be -- Pascals --.

MAILING ADDRESS OF SENDER:

Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield Hills, MI 48303

PATENT NO. <u>6,709,995</u>



PATENT NO: 6,709,995

Page 1 of 3

DATED: March 23, 2004

INVENTOR(S): Joel A. Dyksterhouse

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 1, line 53, "yams" should be -- yarns --.

Column 1, line 55, "vacuums" should be -- vacuum-bag --.

Column 2, line 3 (first occurrence), "In" should be -- in --.

Column 2, line 6, "Incompatible" should be -- incompatible --.

Column 2, line 6, after "incompatible" insert -- with --.

Column 2, line 43, "using" should be -- used --.

Column 5, line 14, "He" should be -- lie --.

Column 5, line 25, "R." should be - R, -.

Column 5, line 49, "Impregnating" should be -- impregnating --.

Column 5, line 50, "withstanding" should be -- withstand --.

MAILING ADDRESS OF SENDER:

Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield Hills, MI 48303

PATENT NO. <u>6,709,995</u>

No. of additional copies



PATENT NO: 6,709,995

Page 2 of 3

DATED: March 23, 2004

INVENTOR(S): Joel A. Dyksterhouse

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 5, line 65, "Coming" should be -- Corning --.

Column 7, line 17, after "in" delete - the -.

Column 7, line 50, "Coming" should be -- Coming --.

Column 9, line 56, after "as" insert -- to --.

Column 10, line 67, "pascals" should be -- Pascals --.

Column 13, line 65, "Is" should be -- is --.

Column 14, line 2, "Coming, Coming" should be -- Coming, Corning --.

Column 14, line 10, "dimensions" should be - dimension -.

Column 14, line 16, "wraps." should be -- wraps, --.

Column 14, line 17, "place" should be -- placed --.

Column 14, line 26, "Coming, Coming" should be - Coming, Corning -.

Column 14, line 41, "Coming" should be -- Coming --.

Column 15, line 33, "Into" should be -- into --.

Column 15, line 59, "Coming, Coming" should be -- Coming, Cornning --.

Column 16, line 13, "place" should be -- placed --.

Column 16, line 57, "Coming, Coming" should be - Corning, Corning -..

MAILING ADDRESS OF SENDER:

Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield Hills, MI 48303 PATENT NO. 6,709,995



PATENT NO: 6,709,995

Page 3 of 3

DATED: March 23, 2004

INVENTOR(S): Joel A. Dyksterhouse

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 17, line 7, "dimensions" should be -- dimension --.

Column 17, Table, line 3 (first occurrence), "95% C.I." should be - 95% C.L. -

Column 17, Table, line 3 (second occurrence), "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 8 (first occurrence), "95% C.I." should be -- 95% C.L. --

Column 17, Table, line 8 (second occurrence), "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 13 (first occurrence), "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 13 (second occurrence), "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 16, "95% C.I." should be - 95% C.L. -.

Column 17, Table, line 20, "95% C.I." should be -- 95% C.L. --.

Column 17, Table, line 25, "0.130" should be -- 0.130" --.

.Column 17, Table, line 33, "64/1" should be -- 64.1 --.

Column 19, line 26, "substantially," should be -- substantially --.

Column 19, line 26, "void" should be -- voids --.

Column 20, line 41, "Inlet" should be -- inlet --.

Column 20, line 51, "pascals" should be -- Pascals --.

MAILING ADDRESS OF SENDER:

Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield Hills, MI 48303

PATENT NO. <u>6,709,995</u>

